

19518

2011-17 Chevy Cruze, 2013 18 Buick Encore L4-1.4L Turbo

- Subject:** Premature Catalytic Converter Failures
- Condition:** PO420 & PO430 Codes. Catalyst Failure
- Cause:** Corrosion or damage to the ground terminal ring from the coils to the engine block.
- Solution:** Carefully inspect and clean the ground rings and connections. Replace terminal rings if necessary.
- Additional Help:** Available from Davico Technical Assistance at 800-422-6046
Additional information: TSB PIP5232C

